SPLIT

DART AEROSPACE LTD	Work Order:	22248	
Description: Frame Weldment	Part Number:	D3330-041	
Dwg: D3330 Rev. A PAGE I	Qty:	4 18	
PF 05.01.17		Page 1 of 1	

nu Bradil				rage 1 of	1
Step	Location	The state of the s	ιBv	Date	Qty
1	DC	Issue Traveler	A.	05.0117	10
2	MFA	Assemble and Weld as per Dwg Dwg D3330 using D3330-041T1  Pick:  Oty Part Number Description 1 D3330-1 Panel M16 387 1 D3330-2 Panel M16 387 1 D3330-5 Panel M16 387 1 D3330-7 Panel M16 387 1 D3330-1 Long Pin Bracket B22260 M16236 CF 1 D3330-13 Short Pin Bracket B22260 M16236 CF 1 D3330-15 Handle B22261 M15925 CF 1 D3330-17 Handle Socket B222 62 M1532 CF 1 D3330-19 Handle Rim B22265 M15990CF Identify as D3330-041	24	*	4
3	QC5	Inspect work to Step 2	#	05.01.20	H
4	FP	Powder Coat Fire Red (Ref: 4.3.5.10) as per QSI 005 4.3	1	05 PZ 16	11
5	QC3	Inspect Powder Coat		0502-18	7
6	ST	Identify and Stock	u	05.00 B	4
7	AC	Cost/Part: _/55. 9/			(
8	DC	Close W/O/55.8/ Inspect Level 21	1 1	05-02-21	4
Rev	Date	Change	Revised		oved
A	05.01.13	THE STATE OF THE S	J/JLM	Apple	//

RELEASED